




**Photo 1** - Looking East from toe of slope that is failing on COS Property  
(Note sediment that is accumulating on the sidewalk and box culvert)





**Photo 2** - Looking West from toe of slope that is failing on COS Property  
(Note erosion and sediment that is accumulating at toe of slope and at sidewalk)